



### THERMITE BRAZE

#### NOTES:

1. CLEAN PIPE TO BRIGHT METAL.
2. THERMITE BRAZE TO BE CADWELL BY ERICO PRODUCTS OR EQUAL.
3. USE PROPER BRAZE ALLOY FOR STEEL.
4. TEST BRAZE BY PULLING ON WIRE & STRIKING BRAZE.
5. COAT BRAZE WITH ROYSTON PRIMER AND "HANDY CAP."

SPECIAL NOTE:  
THERMITE BRAZE KIT  
SUPPLIED BY:  
FARWEST CORROSION CONTROL  
GARDENA, CA.  
(214) 770-6425



APPROVED BY:				
<i>John P. Sullivan</i>		24079 08/15/06		
JOHN P. SULLIVAN CITY ENGINEER		RCE	DATE	
RECOMMENDED:				
<i>Scott Burtz</i>		57875 08/14/06		
ASST. UTIL. DIRECTOR/ENG.		RCE	DATE	
REV	DESCRIPTION	BY	APP'D	DATE

CITY OF ONTARIO

THERMITE BRAZE  
DETAIL

STANDARD  
DRAWING  
NUMBER

**4009**